Snap Printer Changes Test Document

Version 3.41.16.07

Changes in Version 3.41.16.07

FIXES:

❖ ALM #658: SQCR000904 - Ralph Lauren - The SN printed after EOD state show 'O' and 'P' state even the labels printed successfully

Label counting internally was incorrect when the printer was ramping down. Counting internally is meant when the Imager is accounting for tags by commands from the MCB.

❖ ALM #661: No Rmake log found E value in the log file

Label counting internally was incorrectly reported when a new tag started printing and an interlock such as ink out or printhead was opened. Before, it was thought this was a duplicate tag when it was not and there was no physical tag printed. Counting internally is meant when the Imager is accounting for tags by commands from the MCB.

REJECTED:

❖ ALM #660: UA V4 format print log last part missing

The test data provided did not contain a serialized field therefore the data was not reported back to the host.

FEATURES:

NONE