

# Technical Service Bulletin

**July 26, 2021****Model: ADTP1, ADTP2****Author: G. Rawlins/LF****Subject: ADTPx Wireless Card Driver**

Version R3.13 for the ADTP1/ADTP2 printers removed the option to select Wireless mode (Ad-hoc or Infrastructure). The new Silex Wireless Driver does not support Ad-Hoc mode.

**Important:** Before updating firmware to R3.13, be sure the printer has **bootloader version 1.0.12** or greater.

The WiFi mode setting is removed from the printer's front panel, MonarchNet2, Telnet and SNMP. Ad-Hoc Channel and Speed have also been removed.

MonarchNet2 always reports Infrastructure on the test label and in the USB Data Capture header.

To determine which wireless radio card is installed in the printer, from the front panel select:

- ◆ Diagnostics > Version > Wireless (SX-SDCAN or SX-SDCAC is displayed) OR
- ◆ Service Diagnostics > Data Capture (The radio card model has been added to the capture file header).

**Note:** SDCAN is the older card and SDCAC is the newer Silex card.